


FIG. 3






FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10



Search Database	Add Routine	Delete Routine	Exclude Routine	LMOS Messages	Pending Search	Reports
ø.	Α.	D.	×	Ľ	പ്	

LMOS TTN:	Specify Sort Order?	Dist:												Work Code:	Type:	Pair:
PMA Number:	Status:	NPA WC:	Manager:	Supervisor:	Tech:	Work By: From: To:	Pending: From: To:	Dispatch: From: To:	Complete: From: To:	Work Address:	Work Description:	FST Narrative:	Disp Code:	Priority: IST:	Auth #:	Cable:

FIG. 13

		Order?												ork Code:					
—— Search Criteria —	Sort Order	PMA	NPA	Wire Center	District	Manager	Supervisor	Technician	Priority	Status	Authorization	Work By Date	Pending Date	Dispatch Date	Complete Date	TTN —	—— Туре	Work Address	
	PMA Number:	Status:	NPA WC:	Manager:	Supervisor:	Work By: From:	Pending: From:	Dispatch: From:	Complete: From:	Work Address:	Work Description:	FST Narrative:	Disp Code:	Priority:	Cable:				

FIC 14

Complete Date		e g g g	enerouse.	de contra de con	en hom nove	*** O. MA		gw A	4 0 00000	t .	***************************************)	6 a.m.			2-Quit
Dispatch Date Complete Date	00/01/9	6/10/00	6/10/00	00/2/9	00/01/9	and an end			1134	Actual Time:	e vo ove	,		> > > > > > > > > > > > > > > > > > >		N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit
Work By Date	6/10/00	6/10/00	6/10/00	6/3/00	6/10/00		Jones		LMOS TIN:	8::	# Cable Recs: 0	P	gen one ear	ocate Air Leak		S - Select, P - F
PMA Number Auth NPA Wire Ctr Dist Num S Pending Date Work By Date	00/01/9	6/10/00	6/10/00	9/3/00	6/10/00		Supervisor:		404283RTAP01 LMOS TTN:	Estimated Time: 8			enter	Work Description: Run Helium on Buried Cable to Locate Air Leak	broom a	atch, E - Edit, \$
Dist Num S	1773 I	1773	1773	1773	1773	r 144 A 3	10 100	66		Priority: 5	Task: 1 of 1	47A	Work Address: Main Street Work Center	n Helium on	A citica con	es, D -Disp
Wire Ctr	283	283	284	285	285		Smith	6 666 666	Line Reco		asks: N	e: ETA 07	ss: Main S	iption: Ru		- Messag
Auth NPA	404	404	404	404	404		Manager: Smith	Technician: 999 999 999	IST: DPO Line Records:	Pre-Assign: Y	Additional Tasks: N Task: 1 of 1	FST Narrative: ETA 0747A	Work Addre	Work Descr	* * ***	- Cable, M
PMA Number	990603181	990603322	990603187	990601004	990603524		1	~								N - Notes, C

FIG. 15


Complete Date					
Dispatch Date					
PMA Number Auth NPA Wire Ctr. Dist Num S. Pending Date Work By Date Dispatch Date Complete Date	Notes				
Pending Date	Notes —				
tr Dist Num S					
NPA Wire C					
mber Auth					
PMA Nu					

FIG. 16

000602101	1773 D	303 1772 D 6/10/00	3	Lispaicii Daic	Anna Anardina
283	1773 D	6/10/00	6/10/00 6/10/00	6/10/00	
284	1773	9/10/00	6/10/00	6/10/00	
285	1773	6/3/00	6/3/00	00/8/9	
	PMA Cal	PMA Cable Records		6/10/00	,
Cable		Low Pair	High Pair	ž č	,
1612		92	100	1134 Actual Time:	,
				at allower at	common or on seem and concentrators. Does with John AAA.
				9 90 90 90 90 90 90 90 90 90 90 90 90 90	
				of an own town	5


PMA Number	Auth NPA	Wire Ctr	Dist Num	PMA Number Auth NPA Wire Ctr Dist Num S Pending Date	Work By Date	Dispatch Date Complete Date
990603181	404	283	1773 D	D 6/10/00	00/01/9	6/10/00
990603322	404	283	1773	6/10/00	6/10/00	6/10/00
990603187	404	284	1773	6/10/00	6/10/00	6/10/00
990601004	404	285	1773	00/8/9	90/8/9	6/3/00
990603524	404	285	1773	£/10/00	6/10/00	6/10/00 · ·
Created by: Smith	: Smith			Cuiei Messages		
Dispatch Time: 0747	ime: 0747	Cor	Complete Time: 1200	e: 1200		
LMOS Retu	urn Messag	e: 005550	1 Created	LMOS Return Message: 0055501 Created TN 205221RTPPS08	80	
LMOS Tim	LMOS Time Stamp: 06/01/00 07:15:37 pckmcryk	5/01/00 07	:15:37 pck	mcryk		
	FST Narrative: ETA 0747A Work Address: Main Street Work Center	ve: ETA 07	747A Street Work	Center		ANALYSIS VI. W
***************************************	Work Descr	iption: Ru	m Helium o	Work Description: Run Helium on Buried Cable to Locate Air Leak	ocate Air Leak	3 3 3 8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
N - Notes, C	- Cable, M	- Messaç	jes, D -Dis	patch, E - Edit, 9	S - Select, P - I	N - Notes, C - Cable, M - Messages, D -Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit

FIG. 18



Complete Date	THE WAY IN THE PROPERTY AND THE A A ALBERTANISM OF THE PARTY OF THE PA	Ğ-Quit
Dispatch Date 6/10/00 6/10/00 6/3/00 6/3/00	Actual Time:	rint, F - Find,
Work By Date 6/10/00 6/10/00 6/3/00 6/10/00	Manager:SmithSupervisor:JonesTechnician 999 999404283RTAP01LMOS TIN:FST:DPO: Line Records:404283RTAP01LMOS TIN:Pre-Assign:YPriority:5Estimated Time:8Additional Tasks:NTask:1 of 1#Cable Recs:0FST Narrative:ETA 0747AWork Address:Main Street Work CenterWork Description:Run Hellum on Buried Cable to Locate Air Leak	N - Notes, C - Cable, M - Messages, D -Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit
S Pending Date 6/10/00 6/10/00 6/3/00 6/10/00 6/10/00	Supervisor: Jones 99 rds: 404283RTAP01 LMOS TIN: Priority: 5 Estimated Time: 8 Task: 1 of 1 747A Street Work Center un Helium on Buried Cable to Locate A	tch, E - Edit, S
Dist Num S 1773 D 1773 D 1773 1773 1773 1773 1773	Manager: Smith Supervice Technician 999 999 999 1ST: DPO Line Records: 404283RT Pre-Assign: Y Priority: 5 Estimated Additional Tasks: N Task: 1 of 1 FST Narrative: ETA 0747A Work Address: Main Street Work Center Work Description: Run Helium on Burie	Jes, D -Dispa
Wire Ctr 283 283 284 285 285	Smith 1999 999 999 999 999 999 999 999 999 99	Messaç
Auth NPA 404 404 404 404 404	Manager: Smith Technician 999 999 999 IST: DPO Line Records: Pre-Assign: Y Priority: 4 Additional Tasks: N Task: 1 of 1 FST Narrative: ETA 0747A Work Address: Main Street Wo	- Cable, M
PMA Number Auth NPA Wire Ctr Dist Num 990603181 404 283 1773 990603187 404 283 1773 990601004 404 284 1773 990603524 404 285 1773 990603524 404 285 1773		N - Notes, C

FIG. 20



TA
G DA
NION
A PE
PM

ADD

NPA:	Wire Center:	Dist #:	Mgr:	
			Supv:	
			Clear Data? Y	ġ;
Maintenance Center:	enter:		Priority: 5	
Type:	Pre-Assign:	IST:		
				_

Pre-Est: Additional Tasks: Auth:

Task: 1 of 1

Pending Date: Dispatch Date: Work By Date:

Work Code: Work Address: Work Desc:

				Delete I	- Delete Routine Status			
PMA Number NPA Wire Ctr Dist	NPA	Wire Ctr	Dist	Status	Pending Date	Dispatch Date	Pending Date Dispatch Date Complete Date	Type
005845339	205	221 1111 P	11111	Ь	06/01/00			RTAP

Supv: JONES
Pre-Assign: N Maintenance Ctr: 900
Additional Tasks: N Mgr: SMITH Tech: Presurvey Est: 6hr 0 min

Task: 1 of 1

Work Address: TEST Work Desc: TEST

1 record found. Delete? no

ber 1	NPA	Wire Ctr	Dist	Status	Pending Date	PMA Number NPA Wire Ctr Dist Status Pending Date Dispatch Date Complete Date Type	Complete Date	Type
005845339	205	221	===	۵	00/10/90			RTAP
	M _g	Mgr: SMITH			Supv: JONES	NES		
Tech: Presurvey Est: 6hr 0 min	Te : 6hr 0	Tech: r 0 min		e-Assign Iditional	Pre-Assign: N Maintenance Ctr.; 900 Additional Tasks: N	ance Ctr: 900	Task: 1 of 1	of 1
Work Address: TEST Work Desc: TEST	:: TEST EST							

1 record found. Exclude? no

LMOS Time & Date Complete Time & Date 06/01/00 06:15:00 06/01/00 07:47:15 created TTN 55555SRTAP02 06/01/00 11:56:43 created TTN 55555SRTAP13 06/02/00 14:22:56 06/02/00 14:22:56 06/03/00 09:33:40				
EMOS Time & Date 06/01/00 06:15:00 reated TTN 55555RTAP02 06/01/00 08:37:15 reated TTN 55555SRTAP13 06/02/00 14:22:56 reated TTN 55555SRTMISC11	Complete Time & Date	06/01/00 07:47:15	06/01/00 11:56:43	06/03/00 09:33:40
	LMOS Time & Date	06/01/00 06:15:00 reated TTN 55555RTAP02	06/01/00 08:37:15 reated TTN 55555RTAP13	06/02/00 14:22:56 reated TTN 55555RTMISC11

Dist #: Mgr: Supv: Hour From: To: Type: Work Code:

Search Database Add Routine Delete Routine Exclude Routine LMOS Messages Pending Search Reports	A. Address Summary J. Job Type Summary T. Time Summary U. Usage Summary C. Complete Summary W. Actual Time Summary X. Creator of Routine Ticket Y. Craft Work Work Summary
S 4 G X J & J & J & J	

FIG. 27

